



## Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
July 31

### Repair Work

Devil's Slide (post mile 39.14)

- Excavation work continued to provide access for drilling into the cliff below the road for horizontal drains.
- Yerba Buena Construction continued with erosion control work.



Extensive erosion control work above the road

- Electrical contractor St. Francis Electric continued to work on the slide sensor system.



Part of the slide sensor electrical system

Slide Location No. 3 (post mile 39.77)

- 32 H-beams installed to complete this portion of the job.



View of H-beams for the retaining wall